

PHOTOGRAPHIC INTERPRETATION REPORT



AIRCRAFT AT
EMBA AIRFIELD SOUTHWEST
EMBA MISSILE TEST CENTER
USSR

TCS-20258/68

JUNE 1968

COPY 118

2 PAGES

handle via **TALENT-KEYHOLE** control only

Declass Review by
NIMA / DoD

GROUP 1 EXCLUDED FROM
AUTOMATIC DOWNGRADING
AND DECLASSIFICATION

WARNING

This document contains information affecting the national security of the United States within the meaning of the espionage laws U. S. Code Title 18, Sections 793 and 794. The law prohibits its transmission or the revelation of its contents in any manner to an unauthorized person, as well as its use in any manner prejudicial to the safety or interest of the United States or for the benefit of any foreign government to the detriment of the United States. It is to be seen only by personnel especially indoctrinated and authorized to receive information in the designated control channels. Its security must be maintained in accordance with regulations pertaining to TALENT-KEYHOLE Control System.

Handle Via
Talent-KEYHOLE
Control System Only

Approved For Release 2001/09/03 : CIA-RDP80-04759A008500010005-9

TOP SECRET RUFF

TCS-20258/68
June 1968

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

NAME

Aircraft at Emba Airfield Southwest, Emba Missile Test Center

25X1A

COUNTRY	GEO COORDINATES	WAC	BE NO	NPIC NO	COMIREX NO
USSR	48-39-54N 057-58-40E	0236		22-H	None

25X1D

REFERENCES

[REDACTED]

Aircraft were observed for the first time at Emba Airfield Southwest on [REDACTED] photography. Six BEAGLE, one CRATE, one CAB, and eight possible swept-wing aircraft were identified parked at the eastern side of the airfield. The aircraft were not present on [REDACTED] photography. The same types of aircraft have consistently been identified at the main airfield of Emba Missile Test Center.

25X1D

The airfield is 4.4 nm SSW of the main airfield and is oriented in a north-northwest/south-southeast direction. Original construction of the airfield took place between [REDACTED] By [REDACTED] it consisted of a runway 13,220 by 1,045 feet and a parallel taxiway [REDACTED] feet with crossover links at the extremities of the taxiway. Between [REDACTED] ditches were constructed across the northern half of the runway. In [REDACTED] the northern two-thirds was observed regraded into a strip measuring [REDACTED] feet. Support elements such as ILS, GCA, hangars, and POL storage are not present at the airfield.

25X1D


25X1D

25X1D

Handle Via
Talent-KEYHOLE
Control System Only

TOP SECRET RUFF

TPCS-20258/68
June 1968



TOP SECRET RUFF

25X1D

Handle Via
Talent-KEYHOLE
Control System Only

TOP SECRET
Approved For Release 2001/09/03 : CIA-RDP78T04759A008500010005-9

Approved For Release 2001/09/03 : CIA-RDP78T04759A008500010005-9
TOP SECRET